

Theisen & Bonitz Sprint B315VP + 303

Collating + Stitching/Folding/Trimming
machine



Specifications

- first station is not complete and does not work, need to be repair
- checked and cleaned
- machine in good conditon
- two Hohner stitching heads
- no manuals



year of production: 1992



checked and cleaned

